1989 EDITORIAL INDEX

BUILDING ENVELOPE

Choosing a Roofing System — Jan 14
Single-Ply Roofing Manufacturer Index — Jan 18
Built-Up Roofing Manufacturer Index — Jan 22
Polyurethane Foam Manufacturer Index — Jan 22
Exterior Insulation and Finish Systems — Jan 26
Roofing: Replace, Re-Cover or Repair — Jan 36
Building Sealants and Coatings — Jan 48
Weather-Resistant Built-Up Roofing (case study) — Jan 52
Water-Repellent, Breathable Sealant (case study) — Jan 54
Curtainwall Retrofit — Feb 22
Replacement Window Selection — Feb 58
Exterior Conservation Program — Feb 80
Water-Tight Single-Ply Membrane (case study) — Feb 94
Waterproofing Membrane Provides Flexibility (case study) — Feb 96
Solar Control Technology — March 20
Quality Assurance Programs: Roofing — April 50
Roof Inspection Techniques — April 56
Glazing in Reconstruction — July 20
Roof Coatings — Sept 84
Roof System Selection — Sept 96
Replacement Window Criteria — Sept 106
Panels Used to Camouflage Rooftop Systems (case study) — Sept 118
Built-Up Roofing (case study) — Oct 76

BUILDING REMODELING/RETROFIT

Choosing a Roofing System — Jan 14
Single-Ply Roofing Manufacturer Index — Jan 18
Built-Up Roofing Manufacturer Index — Jan 22
Polyurethane Foam Roofing Manufacturer Index — Jan 22
Exterior Insulation and Finish Systems — Jan 26
Roofing: Replace, Re-Cover or Repair — Jan 36
Accessibility Considerations for Door Hardware — Jan 42
Weather-Resistant Built-Up Roofing (case study) — Jan 52
Curtainwall Retrofit — Feb 22
Thermal Storage System Retrofit — Feb 30
Trimming Mechanical and Electrical Budgets — Feb 40
Historic Rehabilitation Guidelines — Feb 50
Replacement Window Selection — Feb 58
Exterior Conservation Program — Feb 80
Lock System Retrofit (case study) — Feb 88
Chiller Control Retrofit (case study) — Feb 92
Watertight Single-Ply Membrane (case study) — Feb 94
Waterproofing Membrane Provides Flexibility (case study) — Feb 96
Multiple Boiler System (case study) — Feb 98
Solar Control Technology — March 20
End-User Installed EMS (case study) — March 74
Building Management System Saves Energy (case study) — March 78
Door Retrofit (case study) — April 112
Creating an Effective Office Lighting Design — May 20
Asbestos and Renovation — May 30
Electronic Access Control — June 20
Electronic Access Control Product Review — June 21
Glazing in Reconstruction — July 20
In-House Construction Management Teams — July 36
Construction Delivery Options — July 44
Elevator Modernization — August 20
The Intelligent Building Concept — August 36
Communications System Planning — August 56
Fiber Optic Networks — August 66
1989 Remodeling Expenditure Survey — Sept 25
Remodeling Case Study: Underground Atlanta — Sept 26
Remodeling Case Study: Beverly Connection — Sept 34
Remodeling Case Study: Carter and MacRae Elementary School — Sept 42
Remodeling Case Study: The Bellevue — Sept 50
Remodeling Case Study: Salt Lake City & County Building — Sept 60
Remodeling Case Study: 745 Fifth Avenue — Sept 66
Remodeling Case Study: St. Paul Medical Center — Sept 76
Roof System Selection — Sept 96
Creating a Public Image — Oct 32
Lighting Retrofit (case study) — Oct 78
Multiple-Site Renovation — Nov 22
Water Chiller Technology — Dec 40
Chiller Retrofit (case study) — Dec 54

ENERGY MANAGEMENT

Exterior Insulation and Finish Systems — Jan 26
Thermal Storage Retrofit — Feb 30
Trimming Mechanical and Electrical Budgets — Feb 40
Replacement Window Selection — Feb 58
Lighting Management Plans — Feb 66
Chiller Control Retrofit — Feb 92
Multiple Boiler System (case study) — Feb 98
Solar Control Technology — March 20
Optimizing EMS Savings — March 30
1989 ASHRAE Energy Awards — March 40
Energy-Efficient Lighting Trends — March 44
Cogeneration Benefits — March 52
Energy Management System Retrofit — March 58
End-User Installed EMS (case study) — March 74
Building Management System Saves Energy (case study) — March 78
Lighting Management — April 72
Uninterruptible Power Supply (case study) — April 108
Uninterruptible Power Supply: Defense Against Computer Downtime — June 48
Glazing in Reconstruction — July 20
Energy Management System (case study) — Sept 116
Energy Management System (case study) — Oct 78
Energy Management (case study) — Dec 54
Thermal Storage (case study) — Dec 56

ENVIRONMENTAL ISSUES

Electrostatic Air Stations (case study) — April 114
Asbestos Lawmaking — May 26
Asbestos and Renovation — May 30
Selecting an Asbestos Contractor — May 36

1989 EDITORIAL INDEX

BUILDING ENVELOPE

Choosing a Roofing System — Jan 14
Single-Ply Roofing Manufacturer Index — Jan 18
Built-Up Roofing Manufacturer Index — Jan 22
Polyurethane Foam Manufacturer Index — Jan 22
Exterior Insulation and Finish Systems — Jan 26
Roofing: Replace, Re-Cover or Repair — Jan 36
Building Sealants and Coatings — Jan 48
Weather-Resistant Built-Up Roofing (case study) — Jan 52
Water-Repellent, Breathable Sealant (case study) — Jan 54
Curtainwall Retrofit — Feb 22
Replacement Window Selection — Feb 58
Exterior Conservation Program — Feb 80
Water-Tight Single-Ply Membrane (case study) — Feb 94
Waterproofing Membrane Provides Flexibility (case study) — Feb 96
Solar Control Technology — March 20
Quality Assurance Programs: Roofing — April 50
Roof Inspection Techniques — April 56
Glazing in Reconstruction — July 20
Roof Coatings — Sept 84
Roof System Selection — Sept 96
Replacement Window Criteria — Sept 106
Panels Used to Camouflage Rooftop Systems (case study) — Sept 118
Built-Up Roofing (case study) — Oct 76

BUILDING REMODELING/RETROFIT

Choosing a Roofing System — Jan 14
Single-Ply Roofing Manufacturer Index — Jan 18
Built-Up Roofing Manufacturer Index — Jan 22
Polyurethane Foam Roofing Manufacturer Index — Jan 22
Exterior Insulation and Finish Systems — Jan 26
Roofing: Replace, Re-Cover or Repair — Jan 36
Accessibility Considerations for Door Hardware — Jan 42
Weather-Resistant Built-Up Roofing (case study) — Jan 52
Curtainwall Retrofit — Feb 22
Thermal Storage System Retrofit — Feb 30
Trimming Mechanical and Electrical Budgets — Feb 40
Historic Rehabilitation Guidelines — Feb 50
Replacement Window Selection — Feb 58
Exterior Conservation Program — Feb 80
Lock System Retrofit (case study) — Feb 88
Chiller Control Retrofit (case study) — Feb 92
Watertight Single-Ply Membrane (case study) — Feb 94
Waterproofing Membrane Provides Flexibility (case study) — Feb 96
Multiple Boiler System (case study) — Feb 98
Solar Control Technology — March 20
End-User Installed EMS (case study) — March 74
Building Management System Saves Energy (case study) — March 78
Door Retrofit (case study) — April 112
Creating an Effective Office Lighting Design — May 20
Asbestos and Renovation — May 30
Electronic Access Control — June 20
Electronic Access Control Product Review — June 21
Glazing in Reconstruction — July 20
In-House Construction Management Teams — July 36
Construction Delivery Options — July 44
Elevator Modernization — August 20
The Intelligent Building Concept — August 36
Communications System Planning — August 56
Fiber Optic Networks — August 66
1989 Remodeling Expenditure Survey — Sept 25
Remodeling Case Study: Underground Atlanta — Sept 26
Remodeling Case Study: Beverly Connection — Sept 34
Remodeling Case Study: Carter and MacRae Elementary School — Sept 42
Remodeling Case Study: The Bellevue — Sept 50
Remodeling Case Study: Salt Lake City & County Building — Sept 60
Remodeling Case Study: 745 Fifth Avenue — Sept 66
Remodeling Case Study: St. Paul Medical Center — Sept 76
Roof System Selection — Sept 96
Creating a Public Image — Oct 32
Lighting Retrofit (case study) — Oct 78
Multiple-Site Renovation — Nov 22
Water Chiller Technology — Dec 40
Chiller Retrofit (case study) — Dec 54

ENERGY MANAGEMENT

Exterior Insulation and Finish Systems — Jan 26
Thermal Storage Retrofit — Feb 30
Trimming Mechanical and Electrical Budgets — Feb 40
Replacement Window Selection — Feb 58
Lighting Management Plans — Feb 66
Chiller Control Retrofit — Feb 92
Multiple Boiler System (case study) — Feb 98
Solar Control Technology — March 20
Optimizing EMS Savings — March 30
1989 ASHRAE Energy Awards — March 40
Energy-Efficient Lighting Trends — March 44
Cogeneration Benefits — March 52
Energy Management System Retrofit — March 58
End-User Installed EMS (case study) — March 74
Building Management System Saves Energy (case study) — March 78
Lighting Management — April 72
Uninterruptible Power Supply (case study) — April 108
Uninterruptible Power Supply: Defense Against Computer Downtime — June 48
Glazing in Reconstruction — July 20
Energy Management System (case study) — Sept 116
Energy Management System (case study) — Oct 78
Energy Management (case study) — Dec 54
Thermal Storage (case study) — Dec 56

ENVIRONMENTAL ISSUES

Electrostatic Air Stations (case study) — April 114
Asbestos Lawmaking — May 26
Asbestos and Renovation — May 30
Selecting an Asbestos Contractor — May 36

Potential Risks and Owner Liability — May 38
Indoor Air Pollution — May 42
Radon: Mixed Perceptions — May 58
PCB Risk Management Strategies — May 64
Indoor Air Quality (case study) — Sept 118

FACILITIES MANAGEMENT

Accessibility Considerations for Door Hardware — Jan 42
Reaping Benefits from Interior Landscaping — Feb 72
HVAC Preventive Maintenance — Feb 76
Optimizing EMS Savings — March 30
Cogeneration Benefits — March 52
Customized Building Management System Financing — March 66
End-User Installed EMS (case study) — March 74
Carpet-Performance Strategies — April 20
Devising a Landscape Management Program — April 30
HVAC Preventive Maintenance Alternatives — April 38
PM Guidelines for Firetube Boilers — April 42
Quality Assurance Programs: Roofing — April 50
Low-Maintenance Design — April 62
Computer-Assisted Maintenance — April 80
After-Hours Emergency Maintenance — April 88
Uninterruptible Power Supply (case study) — April 108
Selecting an Asbestos Contractor — May 36
PCB Risk Management Strategies — May 64
Uninterruptible Power Supply: Defense Against Computer Downtime — June 48
Facility Management Computer Security — June 58
BOMA Convention Coverage — June 64
In-House Construction Management Teams — July 36
Integrated Building Data Base — July 50
Value Engineering: Cost-Effective Construction Management — July 56
Pre-Purchase Property Assessments — July 62
Six Steps to Catastrophe Recovery — July 70
The Intelligent Building Concept — August 36
Facility Management Software — August 44
CAD/CAFM: Technology to Manage Change — August 48
1989 Remodeling Expenditure Survey — Sept 25
Competing in the Office Market — Oct 24
Signage Considerations — Oct 42
Landscape Planning — Oct 48
CAFM Software Product Review — Oct 58
Daycare: The Latest Tenant Perk — Oct 66
HVAC Design Criteria — Oct 72
Multiple-Site Renovation — Nov 22
Instituting a Water Treatment Program — Dec 32

HVAC TECHNOLOGY

HVAC Preventive Maintenance — Feb 76
1989 ASHRAE Energy Awards — March 40
HVAC Preventive Maintenance Alternatives — April 38
HVAC Design Criteria — Oct 72
HVAC Service — Dec 24
Direct Digital Control of HVAC — Dec 48
Thermal Storage (case study) — Dec 56

INTERIOR PLANNING CONSIDERATIONS

Historic Rehabilitation Guidelines — Feb 50
Reaping the Benefits from Interior Landscaping — Feb 72
Carpet-Performance Strategies — April 20
Office Ergonomics — May 50
Barrier-Free Building Design — July 66
Communications System Planning — August 56
Creating a Public Image — Oct 32
Commercial Carpet (case study) — Oct 76
Lighting the Electronic Office — Nov 32
Office Lighting Product Review — Nov 42
Achieving Acceptable Acoustics — Nov 54
A Closer Look at Carpet Fibers — Nov 62
Relocatable Wall Product Review — Nov 72
Access Floor Product Review — Nov 76
Vinyl Flooring (case study) — Nov 78
Rubber Flooring (case study) — Nov 78
Slip-Retardant Vinyl Flooring (case study) — Nov 80
Flooring Helps Provide Sanitary Conditions (case study) — Nov 80

LIFE SAFETY/SECURITY

Lock System Retrofit (case study) — Feb 88
Electronic Access Control — June 20
Electronic Access Control Product Review — June 21
Microprocessor-Based Building Security — June 36
Systematic Exterior Security Planning — June 42
Facility Management Computer Security — June 58
Fire/Life Safety Systems Step into the Electronic Age — June 70
Contract Security — June 75

LIGHTING

Lighting Management Plans — Feb 66
Energy-Efficient Lighting Trends — March 44
Lighting Retrofit Promotes Energy Conservation (case study) — March 76
Gymnasium Relamping Replaces Inefficient Lighting (case study) — March 80
Lighting Management — April 72
Creating an Effective Office Lighting Design — May 20
Automatic Lighting Controls — August 28
Automatic Lighting Controls Product Review — August 29
Predictable Lighting (case study) — Sept 116
Lighting Retrofit (case study) — Oct 78
Lighting the Electronic Office — Nov 32
Office Lighting Product Review — Nov 42

MAINTENANCE, EXTERIOR/INTERIOR

Roofing, Replace, Re-Cover or Repair — Jan 36
Building Sealants and Coatings — Jan 48
Water-Repellant, Breathable Sealant (case study) — Jan 54
HVAC Preventive Maintenance — Feb 76
Watertight Single-Ply Membrane (case study) — Feb 94
Waterproofing Membrane Provides Flexibility (case study) — Feb 96
Carpet-Performance Strategies — April 20
Low-Maintenance Design — April 62
Computer-Assisted Maintenance — April 80
After-Hours Emergency Maintenance — April 88
Hard Floor Maintenance — April 94
Hard Floor Maintenance Product Review — April 96
Antimicrobial Carpet Treatment (case study) — April 104
Exterior Waterproofing (case study) — April 106
Floor Matting (case study) — April 110
Roof Coatings — Sept 84